SOP

QUALITY MANAGEMENT

Method of quality Management

1.PDCA

2.7 Basic Tools of quality


3.PROCESS MAPPING

4.6 s

5.partio /pritotiziroton



Process maping



6S

